

Hitachi Zaxis 30u-2 35u-2 Excavator Workshop Service Repair Manual

Hitachi Zaxis 30u-2 35u-2 Excavator Workshop Service Repair Manual Hitachi applied all its excavator expertise in the design of the new zero-tail mini excavators ZAXIS30U-2 and ZAXIS35U-2. These machines meet customer demands for operating comfort, enhanced safety and easier maintenance. The series complies with the latest emission regulations, noise suppression standards and ROPS/FOPS standards. Operators have superior control over the machine from the relaxed seat. Owners enjoy a lower cost of ownership due to the machine's durability and easy maintenance.



CLICK HERE TO DOWNLOAD!

CANOPY (CABIN) •ROPS/FOPS** •Adjustable reclining seat** •Seat belt** •Wrist rest** •Seat backrest box** •Air conditioner*** •Defroster*** •Windshield wiper*** •Windshield washer*** •Two work lights** •AM/FM radio*** •12 V outlet** •Ashtray*** •Drink holder** •Utility box* •Rear view mirror** •Evacuation hammer*** HYDRAULIC SYSTEM •Hydraulic pilot type control levers •Pilot control shut-off levers •Anti-drift valve for front attachments •Two-speed travel system •Swing parking brake •Travel parking brake •Piping for attachments

Hitachi Zaxis 30u-2 35u-2 Excavator Workshop Service Repair Manual